This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents *will not* correct images, please do not report the images to the Image Problem Mailbox.


100
102
106
108
110
114
112
104
130
125
142
132
206
138
134
146
136
150
200

Figure 1

Figure 3


100
102
110
111
112
206
138
210
204
212
150
146
144
130
134
142
136
202
200
106
108
104



Figure 2


164
110
162
172
174
177
179
170
176
178
176
160

Fig 4b

Fig 4a


102
176
179
172
170
162
108
164
166
100
177
178
160
110
300

Fig 5a


100
LONGER REFILL TUBE EXTENDS TO
BOTTOM OF WATER RESERVOIR
112
190
192
125

Fig 5b


125
192
190
112
WHEN DOLL IS INVERTED,
POSITION OF TUBE OPENING
KEEPS WATER WITHIN RESERVOIR